

Please rate this document after reviewing at the bottom of this page.

INSPECTION

NTC characteristic

1. Measure the resistance of NTC and Heated pad.
NTC resistance - 8.875 - 11.27 kΩ (25°C ±1°C)
Heated pad resistance - 1.95 ± 0.2 Ω (22°C ±1°C)
2. Measure the temperature.
 - The temperature of wheel surface must rise from -20°C to 20°C in 6 minutes.
 - The temperature of wheel surface must reach 38°C in 25 minutes.

* Thanks for your cooperation for the more quality. Please surely rate this document before closing.