

Please rate this document after reviewing at the bottom of this page.

REPLACEMENT

1. Loosen the rear door checker (B) mounting bolt.
2. Detach the clips, then remove the rear door side weatherstrip (A).

Tightening torque :

16.7 - 21.6 N·m (1.7 - 2.2 Kgf·m, 12.3 - 15.9 lb·ft)



3. Install in the reverse order of removal.

Information

Replace any damaged clips.

* Thanks for your cooperation for the more quality. Please surely rate this document before closing.