



Inspection

Visually check for loose mounting bolts.