



Specification

Heated Oxygen Sensor (HO2S) [Banks 1, 2/Sensor 1]

▷ Type: Zirconia (ZrO2) [Linear] Type

▷ Specification

Item	Specification
Heater Resistance (Ω)	2.4 - 4.0 [23°C(73.4°F)]

Heated Oxygen Sensor (HO2S) [Banks 1,2/Sensor 2]

▷ Type: Zirconia (ZrO2) [Binary] Type

▷ Specification

Item	Specification
Heater Resistance (Ω)	3.3 - 4.1 [20°C(68°F)]