


Components



No.	Connector A	Connector B	Connector C
1	Power supply	Cinching motor (+)	Spindle motor (RH)_Close (-)
2	Illumination (Liftgate inner switch)	Liftgate full open switch	Hall sensor (RH)_Power
3	-	Liftgate full lock switch	Spindle (LH) shild_Ground
4	B-CAN (High)	Liftgate half lock switch	Hall sensor (RH)_Ground
5	B-CAN (Low)	Home position switch_Ground	Spindle (RH) shild_Ground
6	Buzzer	Liftgate latch switch _Ground	Hall sensor (LH)_Power
7	-	System ground	Spindle motor (LH)_Close (+)

8	Liftgate motor	Cinching motor (-)	Spindle motor (RH)_Close (+)
9	-	Liftgate open/close switch	Hall sensor 1 (RH)
10	Gear "N" Position	Liftgate inner switch	Hall sensor 2 (RH)
11	-	Home position switch	Hall sensor (LH)_Ground
12	Antipinch strip (LH)_Power	Antipinch strip (LH)_Ground	Hall sensor 1 (LH)
13	Antipinch strip (RH)_Power	Antipinch strip (RH)_Ground	Hall sensor 2 (LH)
14	-	Power ground	Spindle motor (LH)_Close (-)